



## **MANOMETER**

## INTRODUCTION

The device measures Gauge/Differential Pressure from -5000Pa to +5000Pa.

It features 11 selectable units of measure: Pa, hPa, mbar, mmH20, mmHg, inH20, inHg, psi, ozin², bar, kPa.

Additional features include Data Hold, Auto Power-off with disabling function.

Careful use of this meter will provide years of reliable service.

## **SPECIFICATIONS**

Function	Range	Resolution
Pa	5000	1
hPa	50.00	0.01
mbar	50.00	0.01
mH20	509.9	0.1
mmHg	37.50	0.01
inH20	20.07	0.01
inHg	1.476	0.001
psi	0.725	0.001
ozin <sup>2</sup>	11.60	0.01
bar	0.050	0.001
kPa	5.000	0.001

## **GENERAL SPECIFICATIONS**

Display : LCD

**Accuracy** : ±0.3%FS0 (25°C)

**Repeatability** : ±0.2% (Max. ±0.5% FSO)

Linearity/Hysteresis : ±0.29% FSO

Pressure Range : ±5000Pa / ±0.725psi

Maximum Pressure : 2psi

**Response Time** : 0.5 Seconds Typical

Low Battery Indicator: YesOver range Indicator: OLOperating Conditions: 0 to 50°CStorage Conditions: -10 to 60°C

Power Supply : 3 x 1.5V Batteries

MIN/MAX/AVG Recording



Setting Trends. Showing the Way.

www.metravi.com

\*Technical Specifications & Appearance are subjet to change without prior notice