Humidity, Dew Point, Temp., RS232, Data Logger

# HUMIDITY METER

Model: HT-3015 *ISO-9001, CE, IEC1010* 







The Art of Measurement

## **HUMIDITY METER**

Model: HT-3015

### 1. FEATURES

* Humidity + Temperature + Dew point are combined
into one meter, intelligent and professional.
* 0.01 %RH resolution for the humidity reading,
0.01 degree resolution for the humidity reading.
* Fast humidity measuring response time.
* High accuracy and high precision.
* Dew point measurement.
* Manual and auto manual data logger.
* Data logger function with flexible sampling time
selection, can save max. 1000 reading data with
recall.
* Just few panel buttons, easy operation.
* Microprocessor circuit assures maximum possible
accuracy, provides special functions and features.
* Large LCD with two display, easy readout.
* Heavy duty & compact housing case, designed
for easy carry out & operation.
* Records Maximum and Minimum readings with Recall.
* Auto shut off saves battery life.
* Data hold function for freezing the desired value
on display.
* RS 232 PC serial interface.
* Show the humidity & temperature values on the
LCD display at same time.
* Built-in low battery indicator.
Wide humidity & temp. measuring range.
* Separate humidity & temp. probe, easy operation. &
remote measurement.

2-1 General Specificati	ions
-------------------------	------

Circuit	Custom one-chip of microprocessor LSI		
	circuit.		
Display	LCD size: 61 mm x 35 mm		
	dual function LCD display.		
Measurement	Humidity: %RH ( Relative Humidity )		
Unit	Temperature : °C or °F.		
	Dew point : °C or °F.		
Response Time	5 to 30 seconds typically.		
	@ Reach the 85% reading value		
Temperature	Automatic temp. compensation for the		
Compensation	humidity function.		
Sampling Time	Manual	Push the data logger button	
of Data Logger		once will save data one time.	
	Auto	1, 2, 10, 30, 60, 600, 1800,	
		3600 seconds.	
Data Hold	Freeze the display reading.		
Memory Recall	Maximum & Minimum value.		
Sampling Time	Approx. 0.8 second.		

Sampling Time	Approx. 0.8 second.		
Power off	Auto shut off saves battery life or manual		
	off by push button.		
Data Output	RS 232 PC serial interface.		
Operating	0 to 50 ℃.		
Temperature			
Operating	Main instrument: Less than 85% R.H.		
Humidity	Probe: 0 to 95 %RH.		
Power Supply	006P DC 9V battery		
	( Alkaline or Heavy duty type ).		
Power Current	Approx. DC 4.6 mA.		
Weight	306 g/0.67 LB.		
	@ Battery is included.		
Dimension	Main instrument :		
	180 x 72 x 32 mm		
	(7.1 x 2.8 x1.3 inch)		
	Humidity Sensor Probe :		
	197 mm ( 7.8 inch ) in length.		
Accessories	Instruction manual1 PC		
Included	Humidity probe1 PC		
	Carrying case 1 PC		
Optional	RS232 cable/UPCB-01, USB cable/USB-01		
Accessories	Data Acquisitio software, SW-U801-WIN		
	Data Logger software, SW-DL2005		

### 2-2 Electrical Specifications (23±5 °C)

Humidity/ Temperature			
	Range	10 % to 95 % R.H.	
Humidity	Resolution	0.01 % R.H.	
	Accuracy	≥70% RH:	
		± (3% reading + 1% RH).	
		< 70% RH:	
		± 3% RH.	
	Range	0 °C to 50 °C,32 °F to 122 °F.	
Temperature	Resolution	0.01 degree	
	Accuracy	℃ - 0.8 ℃.	
		°F - 1.5 °F.	

<b>Dew Point</b>		
$^{\circ}\mathbb{C}$	Range	-25.3 °C to 48.9 °C
	Resolution	0.01 ℃
°F	Range	-13.5 °F to 120.1 °F.
	Resolution	0.01 °F.

#### Remark :

- \* Dew Point display value is calculated from the Humidity/Temp. measurement automatically.
- \* The Dew Point accuracy is sum accuracy value of Humidity & Temperature measurement..

<sup>\*</sup> Appearance and specifications listed in this brochure are subject to change without notice.